Work Order ID 58337

May 3, 2010 2:33:00 PM

Required Date: 5/07/10

Item ID:

D4010-1

Revision ID:

Item Name:

Bearpaw

Start Date:

5/03/10

Start Qty: 8.00

Req'd Qty: 8.00

Reference:

Approvals:

Process Plan:

QC:

Operation Description

Revision Nbr

Work Center ID Draw Nbr

Sequence ID/

D4010

100

Thermoform

Thermoforming Machine

Memo

HAND FINISHING THERMOFORMING

Cut Blanks to fit frame size

Date:

Date:

105

HandThermo

Hand Finishing Thermoforming

Dry Material

Memo

Dry Sheet as per QSI022 ALEXTRA

240 F Temp:

8:00PH Time IN:

7:00 AM

Accept

Tooling:

0.00

0.00

0.00

0.00

SPC (Y/N):

Set Up/

Run Hours

Stop

Setup Start

Cust Item ID:

Customer:

Draw

Number

Date:

Draw

Rev.

Plan

Code

Date:

Run

Accept

Qty

Start

Reject

Qty

Stop

Reject Number

Insp. Stamp

W/O:			W	ORK ORDER CHAN	IGES					. 4,
DATE	STEP	PRO	OCEDURE CH	ANGE	E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								d.		
					:					
· .										
Part No		PAR #:								
	Re	solution:							Date:	
NCR:		,	WORK ORI	DER NON-CONFORI	MANCE (NCR)				
DATE	STEP	Description of NC	turisi at		ection B	Nam 0	Verific	ation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
•				·						
1										
				,						

Work Order ID 58337

May 3, 2010 2:33:00 PM

Item ID:

D4010-1

5/03/10

Accept



Setup Start

Stop



Revision ID:

Item Name: Bearpaw

Start Date:

Start Qty: 8.00

Required Date: 5/07/10

Req'd Qty: 8.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

Date:

Date:

Run

Start Stop



QC:

Operation

Description

SPC (Y/N): Set Up/

Run Hours

Draw

Number

Draw Plan

Code

Rev.

Reject Accept Qty **Qty**

Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

110

Thermoform

THERMOFORMING MACHINE

Memo

0.00

0.00

Thermoforming Machine

Thermoform as per Dwg. D4010-1 and Folio FTA067 using tool DT 9540

Dwg. Rev. Folio Rev.

120

Quality Control

QC2- Inspect parts off machine FAI/FAIB

0.00

Memo

0.00

Visually inspect for proper formation of each part

130

Memo

QC8- Inspect parts - second check

0.00

0.00

Quality Control



W/O:			WC	RK ORDER CHANG	ES			. *
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					·			
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQA: _	Date: _	
_		solution:						
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR)		
DATE	STEP	Description of NC		Corrective Action Secti		Verification	n Approval	Approval
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
,								
	<u> </u>							
							·	

Page 3

May 3, 2010 2:33:01 PM

Item ID:

D4010-1

Revision ID:

Item Name:

Bearpaw

Start Date:

5/03/10

Start Qty: 8.00



Accept



Setup Start

Stop



Required Date: 5/07/10

Req'd Qty: 8.00

Cust Item ID:

Customer:

Reference: Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start

Stop



QC:

Date:

SPC (Y/N):

Date:

Draw

Rev.

Sequence ID/ **Work Center ID**

140



Thermoform

Thermoforming Machine

Operation Description

Set Up/ **Run Hours**

0.00

Draw Number Plan Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

HAND FINISHING THERMOFORMING

Memo

0.00

1-Trim & Drill to Finished Dimensions as per dwg D4010-1

2- Use wearplate jig DT9542 to transfer drill holes in bearpaw as per dwg and use 0.375" unibite to open holes to finish size.

3- Chamfer all holes on both sides using appropriate 0-flute countersink bit.

145



Hand Finishing Thermoforming

Anneal Material

Memo

0.00

0.00

Anneal trimmed & drilled product at 250 deg. F. for 75 minutes & allow to cool in oven.

	•									
W/O:			W	ORK ORDER CHANG	GES					, E
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				· · · · · · · · · · · · · · · · · · ·			<u>-</u>			
							- 10			
Part No		PAR #:								
	Res	solution:							Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC	In tal at		ction B	C: 0	Verific	cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
•										
					Ì					
	,,			:			11			
				f						
								į		

Page 4,

May 3, 2010 2:33:01 PM

Item ID:

D4010-1

Bearpaw Item Name:

Start Date:

Revision ID:

5/03/10

Start Oty: 8.00

Required Date: 5/07/10

Req'd Qty: 8.00



Accept



Setup Start





Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Date: Date:

Tooling:

SPC (Y/N):

Date: Date: Run Start

Stop

Sequence ID/

Work Center ID

150

Operation Description

QC2- Inspect parts off machine FAI/FAIB

Set Up/ **Run Hours**

0.00

Draw Number

Draw Rev.

Plan Accept Oty Code

Reject Reject Oty

Insp. Number Stamp

Quality Control

Memo

0.00

Check dimensions to ensure conformity to drawing tolerances.

160

Quality Control

QC5- Inspect part completeness to step on W/O

PER D4010

170

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

Memo

0.00

0.00

W/0: 5	8337	WORK ORDER CHANGES					1 1,
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
iolodia	步	more step # 100 (acd) & AFTER 5kp # 140. Makes no serve	M	10.00.07			5 105/12
		Wo Dorte Duy les to les D		·			5 16,5/12

Part No: 1010-1	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:	
Resolution:		Disposition:	QA: N/C Closed	:	Date:	

NCR:		\	WORK OR	DER NON-CONFORMANO	CE (NCR)			
DATE	0750	Description of NC		Corrective Action Section B			Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	- Verification Section C	Chief Eng	Approval QC Inspector
		•	-	١				
				•				
				j.				
					:			
					1			1

Work Order ID 58337

May 3, 2010 2:33:01 PM

Item ID:

D4010-1

Revision ID:

Item Name:

Bearpaw

Start Date:

QC:

5/03/10 Required Date: 5/07/10 Start Qty: 8.00 Req'd Qty: 8.00



Accept



Setup Start

Stop



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Run Start

Stop



Sequence ID/

Work Center ID

180

Memo

Operation

Description

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours**

0.00

Draw Number

Draw Rev.

Plan Accept Qty Code

Reject Qty

Reject Number Stamp

Quality Control

0.00

	•									
W/O:			W	ORK ORDER CHANG	GES					ε
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						,
									7	
								į		
Part No		PAR #:	Fault Cate	egory:	NC	R: Yes	No DQ	A:	Date:	
-		esolution:								
NCR:				ER NON-CONFORM						
DATE	STEP	Description of NC			ction B		Verific	cation	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign 8 Date	Secti		Chief Eng	QC Inspector
					·					
					-					

Picklist Print

May 3, 2010 2:32:58 PM

Work Order ID: 58337

D4010-1

Parent Item Name:

Bearpaw

Comments:

Parent Item:

IPP RevA: New issue DD verified by:EC

IPP Rev B. Improved process Add Step 105 (Drying) & 145 (Annealling) to

routings 10/03/31 DL

Component Item ID/ M-ALXTRAB-S.300

Replacement Mfg/

Purchased

Bin No

Primary

Last

Route 100

Unit of sf

Qty on

Loc Code

Qty per Kit 488.9800

7.104

Start Date: 5/03/10 Start Qty: 8.00

Qty

Status

Required Date: 5/07/10

Required Qty: 8.00

Date

Page 1

Alextra ET 0.300 sheet

Location

therm

113108

Loc Oty

488.98 488.98

	-									
W/O:			W	ORK ORDER CHAN	GES					,
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			. *							
Part No	•	PAR #:	Fault Cat	egory:	NC	R: Yes	No DQ /	\ \ :	Date:	
		solution:								
NCR:				DER NON-CONFORM						
DATE	STEP	Description of NC			ection B		Verific	ation	Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Secti		Chief Eng	QC Inspector
								·		
									,	
				The state of the s						
				·			:			

DART AEROSPACE LTD	Work Order:	58337
~ ~		
Description: Bazzar	Part Number:	
,		
Inspection Dwg: 1) 40(0) Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST THERMOFORMING SECTION

Measured by:	NG	Date: io o	5/	10 -
				

TRIMMING SECTION

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
12.00 "	1/- 0.25"	11.8754	~			
5,50"	7630"	5,50"	~			
9.50"	4- 630"	9.50"				
11.81"	4- 030"	11.81"	レ			
14.69"	4030"	16.70"				
20.94 41	7- 030"	30,90"				·
23,251	7- 030"	23.25				
74.66"	4-0.25"	24.5	V			
2.34"	41-0,25"	2.25	~			
1.0011	4- 0.100"	1.05"	<u></u>			
Ø 1.25"	7-0,13"	1.354	ب			
Ø 0.375"	t- 0.000"	· 8,375"	/			·

Measured by:	Date: 10/05/4
Audited by:	Date: 10/05/1/
Preliminary Approval:	Date:


Rev	Date	Change	Revised by	Approved
В	10.04.14	Added preliminary approval	KJ	

D4010-041 BEARPAW ASSEMBLY (407) OPTIMIZED DESIGN BASED ON FUNCTIONALITY AND TO EASE MANUFACTURING REDESIGNED, ADDED PROVISIONS FOR COMPATIBILITY WITH OEM SKIDTUBES/SADDLES; REDEFINED SOME TOLERANCE 09.11.10 мв 09.11.02 09.10.22 REV. DESCRIPTION BY DATE DESIGN DART AEROSPACE LTD DRAWN DRAWING NO. CHECKED REV. C MFG. APPR. SHEET 1 OF 3 TITLE APPROVED SCALE BEARPAW (407)

COPYRIGHT © 2009 BY DART AEROSPACE LTD


THIS DOCUMENT OF MORTH AMOCOMPORTH, AND B SUPPLE OF THE LEARNESS CORRING
NOT THE SECTION AND HOTOLOGY COUNTY OF EXAMPLES TO THE PERSON OF THE P DE APPR. DATE 09.11.10

W/O:		WORK ORDER CHANGES										
DATE STEP		PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						ļ						
							. The state of the					
Part No	:	PAR #:	Fault Cat	egory:	_ NCF	l: Yes	No DQA	:	Date:			
			Disposition:									
NCR:			WORK ORI	DER NON-CONFORM	ANCE	(NCR)					
DATE	STEP	Description of NC		Corrective Action Section			Verificati			Approval		
	0.2	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sectio		Approval Chief Eng	QC Inspector		
								-				
								1				
							ļ					





Dart Aer	ospa	ce	LI	d
----------	------	----	----	---


W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No		PAR #:	Fault Ca	tegory:	ŅC	R: Yes	No DQ	\;	Date:			
	R	esolution:	on: Disposition:			QA: N/C Closed:						
NCR:			WORK OR	DER NON-CONF	ORMANCI	E (NCF	₹)		-			
DATE	STEP	Description of NC Section A	Corrective Action Section Initial Action Description		Section B	Sign 8	Verific		Approval	Approval		
		Section A	Chief Eng	Chief Eng		Date	Section	on C	Chief Eng	QC Inspector		
					· · · · · · · · · · · · · · · · · · ·							



W/O:		WORK ORDER CHANGES .										
DATE STEP		PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						-						
						-	· · · · · · · · · · · · · · · · · · ·					
				·								
Part No: PAR #:		PAR #:	Fault Category: NC			NCR: Yes No DQA: Date:						
		Disposition: Q/					Date:	Date:				
NCR:		. V	VORK OR	DER NON-C	ONFORMAN	ICE (NC	R)					
DATE	STEP	Description of NC Section A	Initial		Description	Sign	& Sect	cation	Approval Chief Eng	Approval QC Inspector		
			Chief Eng	Ch	ief Eng	Date	9					
		•										
										·		
						}			·			
								-				







L Lacelle

From: Marc Bellavance [mbellavance@dartaero.com]

Sent: June 3, 2010 8:26 AM

To: 'L Lacelle'; 'Mike Petsche'

Subject: RE: 407 beapaws

Well, drawing D4010 Rev. D was revised and released on May 26 to include all the changes discussed

during our investigation and based on Exova's report.

So really, no Eng sign offs are required. In my opinion, QC can inspect per D4010 Rev. C.

Marc Bellavance Mechanical Designer/Technical Support

DART aerospace Ltd.

Tel: 613-632-5200 Ext. 240

Fax: 613-632-9311

E-mail: mbellavance@dartaero.com

Web: <u>www.dartaero.com</u>

Please consider your environmental responsibility before printing this e-mail

The information contained in this transmission is privileged and confidential and intended only for the use of the individual or entity to whom it is addressed. If you are not the intended recipient, you are hereby notified that any distribution, copying, disclosure or taking of any action in reliance on the contents of this transmission is strictly prohibited and review by any individual other than the intended recipient shall not constitute waiver of privilege. If you have received this transmission in error, please notify me immediately and delete the original transmission.

From: L Lacelle [mailto:llacelle@dartaero.com]

Sent: June 3, 2010 7:27 AM

To: 'Mike Petsche'; 'Marc Bellavance'

Subject: 407 beapaws

We have had some 407 bearpawa D4010-041's made by Daryl some time ago that are still sitting near the pkging area waiting for engineering sign off...who can take care of this for me?

Thank You, Linda Lacelle Production Manager Dart Aerospace Ltd